Qtv:

عد الاد

Each

8 Um:

: LANYARD ASSEMBLY

: D269024

: 2/12/2008

: N/A

: B2

D2690 REV. B2

Date

Tuesday, 2/5/2008 11:06:44 AM

Kim Johnston lyser:

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer Job Number : CU-DAR001 Dart Helicopters Services

: 37201

Estimate Number

: 12306

P.O. Number This Issue

Prsht Rev.

: 2/5/2008

: NC

: //

First Issue

: 36250 Previous Run

Written By

Checked & Approved By

Comment

Removed Manufacturer Release 01.08.24

S.O. No. :

Certification SM/EC

Type

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: Loop Sleeve

1.0

CBL460

Comment: Qty.:

2.0000 Each(s)/Unit Total:

16.0000 Each(s)

Loop Sleeve

Pick:

Qty 2

CBL1240

Part Number CBL-460

Description

Loop Sleeve

: SMALL /MED FAB

Comment: Qty.:

Total: 2.0000 f(s)/Unit

16.0000 f(s)

Cable

Pick:

Qty

Part Number CBL-1240

Description

Cable

3.0

2.0

SMALL FAB 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per Dwg D2690

. 4.0

QC5

INSPECT WORK



Comment: INSPECT WORK TO CURRENT STEP

5.0 PACKAGING 1

PACKAGING RESOURCE #



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:



Dart Ae	rospace l	Ltd								
W/O:			W	ORK ORDER CH	ANGES				·	
DATE STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							· · · · · · · · · · · · · · · · · · ·			
Part No:		PAR #:	PAR #: Fault Category:			NCR: Yes No DQA: Date:				
						QA: N	C Closed	d:	_ Date: _	
NCR:		1	NORK OR	DER NON-CONFO	RMANCE	(NCR)			
DATE	OTED	Description of NC		Corrective Action	Section B		Verification		Approval	Approval
	STEP	Section A	Initial Chief Eng	Action Descrip Chief Eng	tion	Sign & Date	Section		Chief Eng	QC Inspector
									i.	
					,					

NOTE: Date & initial all entries

Date:

Tuesday, 2/5/2008 11:06:44 AM

User:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LANYARD ASSEMBLY

Job Number: 37201

Part Number: D269024

Job Number:



Seq. #:

Machine Or Operation:

Description:

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



jun 2008/2/12






Dart Ae	rospace	Ltd									
W/O:			WO	RK ORDER CH	ANGES						
DATE STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
										·	
Part No:		PAR #:	PAR #: Fault Category:			NCR: Yes No DQA: Date:					
						QA: N	/C Closed	d:	_ Date: _		
NCR:		1	WORK ORDE	R NON-CONFO	RMANC	E (NCR)				
DATE	STEP	Description of NC Section A	Corrective Action		Section B		Verification	ation	Approval Chief Eng	Approval QC Inspector	
			Initial Chief Eng	Action Descrip Chief Eng	tion	Sign & Date	Section C				
								į			

NOTE: Date & initial all entries



DESIG	DESIGN DRAWN BY		DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA					
CHEC	HECKED APPROVED		DRAWING NO. REV.	В				
Î	nag	BW	D2690 SHEET 1 OF	F 1				
DATE			TITLE SCA	LE				
97.1	0.02		LANYARD ASSEMBLY	ITS				
Α		97.07.03	NEW ISSUE					
В		97.10.02	REVISED NOTE FOR ADDITIONAL LENGTH	1				
131	at cr	01:08.20	ADD NOTE TO REMOVE 2.25" OF SLEEVE					
\mathbb{R}^2	-A	= 04 06 24	ADDED TOLERANCE					





X = LENGTH IN INCHES

D2690-X

NOTE:

SHOP COPY CUT CABLE 2.50* INCHES LONGER THAN 'X' LENGTHEN

FOLD ENDS TIGHT TO 'X' LENGTH AND CRIMP WITH THE PROPERTY OF T SLEEVE AT END OF LOOSE END OF CABLE WIRFONTROLLED COPY CBL-705 CRIMPING TOO! SUBJECT TO AMENDMENT WITHOUT NOTICE

*ADDITIONAL LENGTH MAY BE NECESSARY IN

SOME APPLICATIONS. CUT AS REQUIRED.

IN SOME CASES, END HAS TO BE CRIMPED AFTER NOTE:

ASSEMBLY WITH ATTACHING PARTS.

DEO's